



• Potential Hazard



Merrimack River Bathymetry
 1.0 Foot Contour Interval
 Mean Lower Low Water Elevations
 Merrimac to Haverhill, Massachusetts

NOTES:
 1. Bathymetry: survey conducted by CR Environmental, Inc. in October 2014.
 2. Base or the photos from MA GIS (2013).
 3. Potential Hazards based on tide gauge water data of features less than 6 feet deep within the navigable channel.

1:8,500

